# Property Disclosure

Case Number: 495-846314
Property Address: 7651 Glen Fls
San Antonio, TX 78239

Insurability: Insurable with Repair Escrow (IE)

| MPR Property Repairs |
|---|
| Repair / Replace Exterior Siding, Carport Posts, Trim, Soffit and Fascia |
| Repair / Replace Electrical System ( Exposed Electrical ) |
| Repair / Replace Exterior Exposed and Damaged Wood |
| Repair / Replace Drywall and Ceilings |
| Repair / Replace Driveway |

| Property Disclosures |
|---|
| Property is NOT located in a FEMA Special Flood Hazard Area. It is the buyers responsibility to verify additional information regarding flood zones and insurance. |
| Property does not have a Homeowners Association (HOA). |
| Property built before 1978 - Lead Based Paint addendum required |
| Property has a Shed/ Storage Building |
| Possible Structural issues have been reported, a Structural inspection recommended to determine the extent, as well as the cost of needed repairs. Repairs to be addressed by the purchaser after closing at the purchaser's expense - Buyer to complete their due diligence and gather all pertinent information regarding the property that may impact their purchase decision |
| Foundation inspection is recommended |
| Property is listed as Insurable with Repair Escrow (IE): Less then $10,000 in Estimated MPR Repairs - Final repair escrow amount to be determined by the buyer's appraisal |

| General Disclosures |
|---|
| **All HUD Homes are sold in their AS-IS condition:** HUD will not make any repairs nor allow the purchaser to complete any repairs prior to closing. **FOR YOUR PROTECTION GET A HOME INSPECTION** |
| Permission to activate utilities for purposes of the home inspection may be requested from the HUD Field Service Manager after the HUD-9548 sales contract is executed by the seller. Fees for activation may apply. |
| Properties being purchased with FHA insured financing will require a termite inspection and possible treatment. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or treatment has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection and treatment prior to closing. |
| Properties built prior to 1978 and being purchased with FHA insured financing will require a lead-based paint inspection and possible stabilization. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or stabilization has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection ,stabilization and clearance letter prior to closing. |

*This information is accurate based on the data available at the time of listing, and is deemed reliable but not*

*guaranteed. All information should be independently verified.*