Property Disclosure

Case Number: 023-922284 Insurability: Uninsurable (UI)

Property Address: 4119 Indian Bend Rd
Snowflake, AZ 85937

MPR Property Repairs
Inspect and Repair Damaged Foundation
Repair / Replace Drywall and Ceilings
Repair / Replace Roof
Repair / Replace Plumbing System (Failed Pressure Test)
Installation of hauled water cistern and pump
Repair / Replace Electrical System (Missing Components)
Repair / Replace Smoke and CO Detectors
Repair / Replace HVAC System (Missing Components)

Property Disclosures
Possible Structural issues have been reported, a Structural inspection recommended to determine the extent, as well as the cost of needed repairs. Repairs to be addressed by the purchaser after closing at the purchaser's expense.
Property does not have a Homeowners Association (HOA).
Property is being sold in As-Is condition, but if any personal property item is present. it may or may not be removed prior to closing of sale
Property serviced by a Non-Public Utility: Hauled/Typical
Property serviced by a Non-Public Utility: Septic/Typical
Foundation inspection is recommended
Water can NOT be activated for Purchaser Inspection per HUD Field Service Manager
Property is listed as Uninsurable: Estimated MPR Repairs Exceed $10,000

General Disclosures
All HUD Homes are sold in their AS-IS condition: HUD will not make any repairs nor allow the purchaser to complete any repairs prior to closing. **FOR YOUR PROTECTION GET A HOME INSPECTION**
Permission to activate utilities for purposes of the home inspection may be requested from the HUD Field Service Manager after the HUD-9548 sales contract is executed by the seller. Fees for activation may apply.
Properties being purchased with FHA insured financing will require a termite inspection and possible treatment. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or treatment has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection and treatment prior to closing.
Properties built prior to 1978 and being purchased with FHA insured financing will require a lead-based paint inspection and possible stabilization. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or stabilization has begun, the purchaser will be responsible for reimbursing HUD

General Disclosures

for the cost of the inspection ,stabilization and clearance letter prior to closing.

This information is accurate based on the data available at the time of listing, and is deemed reliable but not guaranteed. All information should be independently verified.