Property Disclosure

Case Number: 221-594325
Property Address: 184 Mini Road
Opelousas, LA 70570

Insurability: Uninsurable (UI)

MPR Property Repairs
Repair / Replace Plumbing System (Failed Pressure Test)
Repair / Replace Exterior Trim, Soffit and Fascia
Repair / Replace Fireplace Exhaust
Repair / Replace Damaged Support posts on Carport
Repair / Replace Drywall and Ceilings
Repair / Replace Siding and Skirting
Repair / Replace Flooring - Exposed Sub-floor
Repair / Replace all Missing/Damaged Light Fixtures
Repair / Replace Damaged Cabinets

Property Disclosures
Property is NOT located in a FEMA Special Flood Hazard Area. It is the buyers responsibility to verify additional information regarding flood zones and insurance.
Property does not have a Homeowners Association (HOA).
Property is a Manufactured Home
Appraisal confirms HUD Tags NTA 1428993 and NTA 1428994 are attached to structure
Property serviced by a Non-Public Utility: Septic
Property serviced by a Non-Public Utility: Community
Water can NOT be activated for Purchaser Inspection per HUD Field Service Manager
Property is listed as Uninsurable: Estimated MPR Repairs Exceed $10,000

General Disclosures
All HUD Homes are sold in their AS-IS condition: HUD will not make any repairs nor allow the purchaser to complete any repairs prior to closing. **FOR YOUR PROTECTION GET A HOME INSPECTION**
Permission to activate utilities for purposes of the home inspection may be requested from the HUD Field Service Manager after the HUD-9548 sales contract is executed by the seller. Fees for activation may apply.
Properties being purchased with FHA insured financing will require a termite inspection and possible treatment. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or treatment has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection and treatment prior to closing.
Properties built prior to 1978 and being purchased with FHA insured financing will require a lead-based paint inspection and possible stabilization. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or stabilization has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection ,stabilization and clearance letter prior to closing.

This information is accurate based on the data available at the time of listing, and is deemed reliable but not guaranteed. All information should be independently verified.