Clear Form

Property Listing Disclosure

RAINE

HUD Case Number: 461-498575

Property Address: 2375 PRESSLEY RD. CHESTER, SC 29706

MPR PROPERTY REPAIRS Repair escrow, when applicable, is to be determined by the underwriting mortgagee, per HUD Handbook 4000.0 and ML 2015-17
Repair/replace electrical
Repair/replace plumbing
Repair exterior siding & trim
Repair/replace HVAC
Repair/replace flooring
Repair/replace porch rails & gazebo
Repair settlement cracks and stabilize

PROPERTY DISCLOSURES
This property is listed as Uninsurable
Property is a manufactured home
Property is serviced by well & septic
Property is on acreage. Survey or plat map recommended
Foundation and/or structural inspection recommended
Manufactured home is uninsurable due to missing and/or damaged HUd labels
The buyer is responsible for all costs associated with inspections and cost to cure

GENERAL DISCLOSURES
All HUD homes are sold AS-IS. HUD will not make any repairs nor allow the purchaser to complete any repairs prior to closing. **FOR YOUR PROTECTION GET A HOME INSPECTION**
Utility activation requests (submitting after contract execution) must be approved by HUD's Field Service Manager prior to activation. In cases where plumbing or electrical deficiencies exist, approval for activation may be denied. Repairs will not be made for the purpose of utility activation.
All properties built prior to 1978 utilizing FHA financing will require a Lead Based Paint (LBP) Inspection and possible stabilization.
Should the purchaser elect to change financing from FHA to any other method of financing or cash after LBP/Termite inspections and/or treatments have begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection, treatment and clearance prior to closing.
FHA repair escrow amounts are not a credit from the seller to the buyer. Escrow items represent the minimum property requirements as required by FHA to bring the property into standards that will allow it to meet FHA funding eligibility. All repair costs are financed into the mortgage and are the responsibility of the buyer.

This information is accurate based on the data available at the time of listing and is deemed reliable, but not guaranteed. All information should be independently verified.