Property Disclosure

Case Number: 512-486315
Insurability: Uninsurable (UI)
Property Address: 150 Hunters Dr
Vidor, TX 77662

MPR Property Repairs
Repair / Replace HVAC System
Repair / Replace Electrical System
Repair / Replace Plumbing System
Repair Damaged Foundation
Repair / Replace Roof, Flashing, Gutters and Downspouts
Electrical Service to be Activated

Property Disclosures
Possible Structural issues have been reported, a Structural inspection recommended to determine the extent, as well as the cost of needed repairs. Repairs to be addressed by the purchaser after closing at the purchaser's expense - Buyer to complete their due diligence and gather all pertinent information regarding the property that may impact their purchase decision
Property is located in a FEMA Special Flood Hazard Area. It is the buyers responsibility to verify additional information regarding flood zones and insurance.
Property does not have a Homeowners Association (HOA).
Property serviced by a Non-Public Utility: septic
Property serviced by a Non-Public Utility: well
Property is listed as Uninsurable: Estimated MPR Repairs Exceed $10,000

General Disclosures
All HUD Homes are sold in their AS-IS condition: HUD will not make any repairs nor allow the purchaser to complete any repairs prior to closing. **FOR YOUR PROTECTION GET A HOME INSPECTION**
Permission to activate utilities for purposes of the home inspection may be requested from the HUD Field Service Manager after the HUD-9548 sales contract is executed by the seller. Fees for activation may apply.
Properties being purchased with FHA insured financing will require a termite inspection and possible treatment. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or treatment has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection and treatment prior to closing.
Properties built prior to 1978 and being purchased with FHA insured financing will require a lead-based paint inspection and possible stabilization. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or stabilization has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection ,stabilization and clearance letter prior to closing.

This information is accurate based on the data available at the time of listing, and is deemed reliable but not guaranteed. All information should be independently verified.