Property Condition Report

Case Number:	023-957679	**Contract Area:**	3S
Current Step:	1c-Ready to Show Condition	**Address:**	26776 N ROSE RD
Step Date:	10/26/2026	**City, St Zip:**	MEADVIEW, AZ 86444-0000
HOC:	Santa Ana		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**Damaged**	**HVAC tested and functional?:**	No	Generator/220 Plug/Breaker Panel Visible damage on exterior unit System Damaged/Missing components
--Heating/Furnace:	**N/A**			
--HVAC System Duct:	**N/A**			System Damaged/Missing components
Electrical Wiring:	**Damaged**	**Electric supply tested and functional?:**	No	System Damaged/Missing major electrical components Could not text. Was popping generator
--Other:	**N/A**			
--Other:	**N/A**			
Stove/Range/Oven:	**Missing**	**Built-in appliances tested and functional?:**	No	Appliances Damaged/Missing; could not test. Missing
--Kitchen Cabinets:	**OK**			
--Other:	**N/A**			
Plumbing:	**Damaged**	**Water supply tested and functional?:**	No	System missing components; could not test The main line off the pump is broken and missing
--Sink:	**OK**			
--Other:	**N/A**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	Inspected HWH components; pass with no deficiencies found
Sewer/Septic System:	**N/A**	**Sanitary & plumbing system functional?:**	Yes	Pour Water/Antifreeze in Drains; Pass
--Toilet:	**OK**			
--Other:	**N/A**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Inspected peaks, valleys, ridge lines/caps, chimneys, soffits, decking, boots and vents; Pass with no deficiencies found
--Other:	**N/A**			