Property Condition Report

Case Number:	042-837628	**Contract Area:**	5S
Current Step:	1c-Ready to Show Condition	**Address:**	24259 LILAC RD
Step Date:	07/31/2026	**City, St Zip:**	WILLITS, CA 95490-0000
HOC:	Santa Ana		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**N/A**	**HVAC tested and functional?:**	No	System damaged/missing major electrical components
--Heating/Furnace:	**N/A**			
--HVAC System Duct:	**N/A**			
Electrical Wiring:	**Damaged**	**Electric supply tested and functional?:**	No	System damaged/missing major electrical components
--Other:	**N/A**			
--Other:	**N/A**			
Stove/Range/Oven:	**Missing**	**Built-in appliances tested and functional?:**	No	Appliances damaged/missing could not test
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**Damaged**	**Water supply tested and functional?:**	No	Pressure test
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**Missing**	**Water heater functional?:**	No	MISSING
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	Antifreeze
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Inspected peaks, valleys, ridge lines/caps, chimneys, soffits, decking, boots and vents all pass no deficiencies found
--Other:	**OK**			