Property Condition Report

Case Number:	047-050084	**Contract Area:**	5S
Current Step:	1c-Ready to Show Condition	**Address:**	1517 S KLEIN AVE
Step Date:	09/03/2026	**City, St Zip:**	REEDLEY, CA 93654-0000
HOC:	Santa Ana		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	Power is on
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	Power is on
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**Missing**	**Built-in appliances tested and functional?:**	Yes	Power is on
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	No	Water was already turned off.
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	It appears to be in good condition.
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	System is winterized.
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	No sign of leaks.
--Other:	**OK**			