Property Condition Report

Case Number:	049-189362	**Contract Area:**	5S
Current Step:	3a-Disposition Pending	**Address:**	2603 CASCADE TRAIL
Step Date:	09/17/2026	**City, St Zip:**	COOL, CA 95614-0000
HOC:	Santa Ana		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	N/A	N/A-VISUAL
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	N/A	N/A-VISUAL
--Other:	**N/A**			
--Other:	**N/A**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	N/A	N/A-VISUAL
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	N/A	N/A-VISUAL
--Sink:	**OK**			
--Other:	**N/A**			
Water Heater:	**OK**	**Water heater functional?:**	N/A	N/A-VISUAL
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	N/A	N/A-VISUAL
--Toilet:	**OK**			
--Other:	**N/A**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Inspected peaks, valleys, ridge lines/caps, chimneys, soffits, decking, boots and vents all pass no deficiencies found
--Other:	**N/A**			