Property Condition Report

Case Number:	138-117715	**Contract Area:**	3A
Current Step:	2-Appraisal Complete	**Address:**	6637 S RHODES AVE 02
Step Date:	09/21/2026	**City, St Zip:**	CHICAGO, IL 60637-0000
HOC:	Atlanta		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**Missing**	**HVAC tested and functional?:**	No	AC Unit Missing Continuity Testing Revealed Damages
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**Damaged**	**Electric supply tested and functional?:**	No	Continuity Testing Revealed Damages
--Other:	**N/A**			
--Other:	**N/A**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	No	Continuity Testing Revealed Damages
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**Damaged**	**Water supply tested and functional?:**	No	Pressure Tested with compressor and HWH components FAIL: deficiencies noted
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	Pressure Tested with compressor and HWH components PASS: no deficiencies found
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	Poured Antifreeze in Drains: PASS
--Toilet:	**OK**			
--Other:	**N/A**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Inspected peaks, valleys, ridge lines/caps, chimneys, soffits, decking, boots and vents by walking the roof. Pass, no deficiencies found
--Other:	**OK**			