Property Condition Report

Case Number:	151-946147	**Contract Area:**	4A
Current Step:	2-Appraisal Complete	**Address:**	5868 HILLSIDE AVE
Step Date:	08/13/2026	**City, St Zip:**	INDIANAPOLIS, IN 46220-0000
HOC:	Atlanta		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	Continuity
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	Continuity
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**Damaged**	**Built-in appliances tested and functional?:**	No	Damaged
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	Yes	Pressure test
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	Pressure test
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	Pour test
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	No visible damages
--Other:	**OK**			