Property Condition Report

Case Number:	181-367811	**Contract Area:**	2D
Current Step:	1c-Ready to Show Condition	**Address:**	342 E 6TH AVE
Step Date:	10/07/2026	**City, St Zip:**	GARNETT, KS 66032-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	Systems receive power, but are well past the end of their life expectancy.
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	Pass
--Other:	**N/A**			
--Other:	**N/A**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	Appliance receives power but is not recommended to use
--Kitchen Cabinets:	**OK**			
--Other:	**N/A**			
Plumbing:	**OK**	**Water supply tested and functional?:**	Yes	Pressure test didn't pass, but no visible issues.
--Sink:	**OK**			
--Other:	**N/A**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	Pass
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	Pass
--Toilet:	**OK**			
--Other:	**N/A**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Pass
--Other:	**N/A**			