Property Condition Report

Case Number:	221-655870	**Contract Area:**	2D
Current Step:	1c-Ready to Show Condition	**Address:**	4417 CHATAIGNIER RD
Step Date:	10/31/2026	**City, St Zip:**	VILLE PLATTE, LA 70586-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**N/A**	**HVAC tested and functional?:**	N/A	None
--Heating/Furnace:	**N/A**			
--HVAC System Duct:	**N/A**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	Meter allowing low voltage to pass into breaker box
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**Missing**	**Built-in appliances tested and functional?:**	N/A	Missing
--Kitchen Cabinets:	**OK**			
--Other:	**Missing**			
Plumbing:	**N/A**	**Water supply tested and functional?:**	No	Not able to locate water meter, not able to access HWT
--Sink:	**N/A**			
--Other:	**N/A**			
Water Heater:	**N/A**	**Water heater functional?:**	N/A	Not able to access, vanity will have to be uninstalled and removed to create access
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	N/A	None
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	None
--Other:	**OK**			