Property Condition Report

Case Number:	222-247979	**Contract Area:**	2D
Current Step:	1c-Ready to Show Condition	**Address:**	6597 OAK VALLEY DR
Step Date:	10/07/2026	**City, St Zip:**	SHREVEPORT, LA 71107-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	HVAC SYSREM PRESENT AND INTACT
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	SYTEM CONTUNUITY TESTED AND IS FUNCTIONAL
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	ALL EXISTING APPLIANCES IN WORKING CONDITION
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	Yes	PLUMBING PRESSURE TESTED AND HELD
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	WATER HEATER PRESENT AND IN WORKING CONDTION
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	ALL DRAINS FORCE FLUSHED AND PASSING FLUID PROPERLY
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	ROOF HAS NO VISIBLE DAMAGE NOR INTERIOR WATER INTRUSION
--Other:	**OK**			