Property Condition Report

Case Number:	271-932899	**Contract Area:**	5D
Current Step:	2-Appraisal Complete	**Address:**	1710 E OAKLAND AVE
Step Date:	10/26/2026	**City, St Zip:**	AUSTIN, MN 55912-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	Utilities On
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	Could not test due to outdated electrical (Knob and Tube, Fuse box) but power on
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	Appliances Damaged/Missing; could not test.
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	Yes	Water on; Pass
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**Damaged**	**Water heater functional?:**	No	Inspected HWH components; fail with deficiencies noted.
Sewer/Septic System:	**Damaged**	**Sanitary & plumbing system functional?:**	No	Pour Water/Antifreeze in Drains; Fail.
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Inspected peaks, valleys, ridge lines/caps, chimneys, soffits, decking, boots and vents; Pass with no deficiencies found
--Other:	**OK**			