Property Condition Report

Case Number:	291-627134	**Contract Area:**	2D
Current Step:	1c-Ready to Show Condition	**Address:**	200 WAGONWHEEL DR
Step Date:	07/16/2026	**City, St Zip:**	CAMDENTON, MO 65020-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	Generator, back feed system
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	Generator, backfeed
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	Generator, backfeed
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	Yes	Pressure test passed
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	Visually inspected, no noted defects
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	Antifreeze poured, no noted defects
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Visually inspected peaks, hips, valleys no noted defects
--Other:	**OK**			