Property Condition Report

Case Number:	292-496847	**Contract Area:**	2D
Current Step:	1c-Ready to Show Condition	**Address:**	5928 LAURA AVE
Step Date:	10/26/2026	**City, St Zip:**	SAINT LOUIS, MO 63136-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	HVAC appears to be intact
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	Power is active and in good working condition. Panel is very old - fuse panel.
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	Appliances appear to be intact
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	Yes	Water supply line is intact and passed pressure test
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	Water heater is intact and fucntional
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	Sanitary system is intact and fucntioanl
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Roof is very old but in fair condition
--Other:	**OK**			