Property Condition Report

Case Number:	292-785601	**Contract Area:**	2D
Current Step:	1c-Ready to Show Condition	**Address:**	22287 MUSE RD
Step Date:	08/27/2026	**City, St Zip:**	WRIGHT CITY, MO 63390-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	power on at time of inspection
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	power on at time of inspection
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	power on at time of inspection. All appliances responded
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	Yes	upon adding pressure no apparent leaks at this time
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	no rusting appearance
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	upon adding water/antifreeze the drains passed
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	inspected from ground level
--Other:	**OK**			