Property Condition Report

Case Number:	292-807585	**Contract Area:**	2D
Current Step:	1c-Ready to Show Condition	**Address:**	1272 BONHEUR DR
Step Date:	11/05/2026	**City, St Zip:**	SAINT LOUIS, MO 63146-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	HVAC appears to be intact and functional
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	Panel appears to be intact and functional
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	Built in appliances appear to be intact
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	No	washer shut of valve is damaged. pressure did not hold.
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	Water heater appears to be intact
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	Sanitary system appears to be intact
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Roof appears to be in fair condition
--Other:	**OK**			