Property Condition Report

Case Number:	292-810946	**Contract Area:**	2D
Current Step:	1c-Ready to Show Condition	**Address:**	505 W MAIN ST
Step Date:	08/27/2026	**City, St Zip:**	PARK HILLS, MO 63601-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	HVAC appears to be intact and functional
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	Electric is on and panel is intact
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**Missing**	**Built-in appliances tested and functional?:**	N/A	no appliances present
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	Yes	water supply line is intact
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	Water heater appears to be intact
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	Sanitary system is intact
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Roof is in fair condition
--Other:	**OK**			