Property Condition Report

Case Number:	387-235970	**Contract Area:**	5A
Current Step:	1c-Ready to Show Condition	**Address:**	16741 SPRINGS MILL RD
Step Date:	07/21/2026	**City, St Zip:**	LAUREL HILL, NC 28351-0000
HOC:	Atlanta		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	N/A	Property currently winterized, no utilities on, system appears functional.
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	N/A	Property currently winterized, no utilities on, system appears functional.
--Other:	**N/A**			
--Other:	**N/A**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	Property currently winterized, no utilities on, system appears functional.
--Kitchen Cabinets:	**OK**			
--Other:	**N/A**			
Plumbing:	**OK**	**Water supply tested and functional?:**	N/A	Property currently winterized, no utilities on, system appears functional.
--Sink:	**OK**			
--Other:	**N/A**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	Property currently winterized, no utilities on, system appears functional.
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	Property currently winterized, no utilities on, system appears functional.
--Toilet:	**OK**			
--Other:	**N/A**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	No visible issues, no signs of leaks
--Other:	**N/A**			