Philadelphia Department of Public Health Lead Paint Inspection Record
Lead and Healthy Homes Program

Address Inspected	Case #	
11919 WALDEMIRE DR, 19154	**446-364818**	
Date of Inspection	Date Report Typed	Report Code
9/28/2026	**10/5/2026**	**RC**
Inspector	Clerk	Census Tract
William.Copeland		**036202**
Owners Name	Owners Address	
HUD	**100 Penn Square East Phila., PA 19107**	

A Visual Abatement Inspection of the exterior of this property tested on 2026-08-07 indicates that the lead hazard removal work has been completed.

Lead Paint Removed Correctly.

You must repaint the areas where lead hazards were removed according to the Department Regulation and Specifications before the property can be placed in compliance.

Authorized Signature: Turquoise Martin **Date:** **10/5/2026**

Philadelphia Department of Public Health Lead Paint Inspection Record
Lead and Healthy Homes Program

Address Inspected	Case #	
11919 WALDEMIRE DR, 19154	**446-364818**	
Date of Inspection	Date Report Typed	Report Code
9/28/2026	**10/5/2026**	**RS**
Inspector	Clerk	Census Tract
William.Copeland		**036202**
Owners Name	Owners Address	
HUD	**100 Penn Square East Phila., PA 19107**	

A Visual Repainting Inspection of this property indicates that those areas tested on 2026-08-07 where the lead hazards were abated have been repainted correctly.

All areas have also been cleaned of visible dust, paint chips, and debris.

No dust wipes required. Lead found only on exterior of property.

The proprty is in compliance with the Philadelphia Code and Regulations of the Department of Public Health.

Authorized Signature: Turquoise Martin **Date:** **10/5/2026**