Property Condition Report

Case Number:	461-700772	**Contract Area:**	5A
Current Step:	1c-Ready to Show Condition	**Address:**	312 WALTHAM ABBY RD
Step Date:	07/02/2026	**City, St Zip:**	COLUMBIA, SC 29212-0000
HOC:	Atlanta		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	GENERATOR TESTED SYSTEM POERED UP
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	GENERATOR TESTED SYSTEM POERED UP
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	GENERATOR TESTED SYSTEM POERED UP
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	No	POURED WATER IN DRAINS NO ISSUE NOTED
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	No	WATER HEATER MISSING
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	POURED WATER INTO DRAINS
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	NO ACTIVE ROOF LEAK
--Other:	**OK**			