Property Condition Report

Case Number:	492-901319	**Contract Area:**	1D
Current Step:	2-Appraisal Complete	**Address:**	808 FLAMINGO RD
Step Date:	02/12/2026	**City, St Zip:**	GRANBURY, TX 76049-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	Continuity tested, passed
--Heating/Furnace:	**OK**			Continuity tested, passed
--HVAC System Duct:	**OK**			Continuity tested, passed
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	Continuity tested, passed
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	Continuity tested, passed
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**Damaged**	**Water supply tested and functional?:**	No	Pressure tested, FAILED. System held 20-30psi
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**Damaged**	**Water heater functional?:**	No	Visual inspection, WATER LEAK IN HOT WATER LINE.
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	Pressure tested, passed. System held 20-30psi. Poured antifreeze down drains, passed
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Good condition
--Other:	**OK**			