Property Condition Report

Case Number:	511-310602	**Contract Area:**	1D
Current Step:	2-Appraisal Complete	**Address:**	3985 FM 2625 E
Step Date:	09/17/2026	**City, St Zip:**	MARSHALL, TX 75672-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	continuity testing - passed HVAC continuity testing passed HVAC continuity testing passed
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	continuity testing - passed Rear 2nd floor under construction. BB not connected.
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	continuity testing - passed gas stove present
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**Damaged**	**Water supply tested and functional?:**	No	System will not hold pressure for >30 min.
--Sink:	**Missing**			
--Other:	**N/A**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	gas water heater - Visual inspection pass
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	Gravity flush w/o issue Pour anti freeze down drain pass
--Toilet:	**OK**			
--Other:	**N/A**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Intact - no evidence of leaking
--Other:	**N/A**			