Property Condition Report

Case Number:	512-567772	**Contract Area:**	2D
Current Step:	1c-Ready to Show Condition	**Address:**	1105 5TH ST
Step Date:	10/30/2026	**City, St Zip:**	HEMPSTEAD, TX 77445-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	No	Not tested.
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	No	Not tested.
--Other:	**N/A**			
--Other:	**N/A**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	No	Not tested.
--Kitchen Cabinets:	**OK**			
--Other:	**N/A**			
Plumbing:	**OK**	**Water supply tested and functional?:**	Yes	Pressure test performed during winterization; gauge photo provided.
--Sink:	**OK**			
--Other:	**N/A**			
Water Heater:	**OK**	**Water heater functional?:**	N/A	Not tested.
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	No	Not tested. Toilets winterized with antifreeze.
--Toilet:	**OK**			
--Other:	**N/A**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	Roof in good condition.
--Other:	**N/A**			