Property Condition Report

Case Number:	513-253253	**Contract Area:**	1D
Current Step:	2-Appraisal Complete	**Address:**	312 S MOCKINGBIRD L
Step Date:	09/15/2026	**City, St Zip:**	KEENE, TX 76059-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	Continuity tested, passed
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	Continuity tested, passed
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**OK**	**Built-in appliances tested and functional?:**	Yes	Continuity tested, passed
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	Yes	pressure tested, passed. system held 20-30psi
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	visual inspection, passed
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	pressure tested, passed. system held 20-30psi
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	good condition
--Other:	**OK**			