Property Condition Report

Case Number:	513-274362	**Contract Area:**	1D
Current Step:	2-Appraisal Complete	**Address:**	1109 NUGENT ST
Step Date:	10/15/2026	**City, St Zip:**	BOWIE, TX 76230-0000
HOC:	Denver		

Property Condition Report

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-Conditioner:	**OK**	**HVAC tested and functional?:**	Yes	GENERATOR TESTED. FUNCTIONAL AT TIME OF INSPECTION GENERATOR TESTED. FUNCTIONAL AT INSPECTION GENERATOR TESTED. FUNCTIONAL AT INSPECTION
--Heating/Furnace:	**OK**			
--HVAC System Duct:	**OK**			
Electrical Wiring:	**OK**	**Electric supply tested and functional?:**	Yes	GENERATOR TESTED. FUNCTIONAL AT TIME OF INSPECTION
--Other:	**OK**			
--Other:	**OK**			
Stove/Range/Oven:	**Missing**	**Built-in appliances tested and functional?:**	No	MISSING OVEN/RANGE
--Kitchen Cabinets:	**OK**			
--Other:	**OK**			
Plumbing:	**OK**	**Water supply tested and functional?:**	Yes	PRESSURE TESTED. SYSTEM HELD PRESSURE AT TIME OF INSPECTION
--Sink:	**OK**			
--Other:	**OK**			
Water Heater:	**OK**	**Water heater functional?:**	Yes	WATER HEATER DRAINED. FUNCTIONAL AT TIME OF INSPECTION
Sewer/Septic System:	**OK**	**Sanitary & plumbing system functional?:**	Yes	SANITARY AND PLUMBING SYSTEMS FUNCTIONAL AT TIME OF INSPECTION
--Toilet:	**OK**			
--Other:	**OK**			
Roof:	**OK**	**Roofing in acceptable condition?:**	Yes	ROOF IN ACCEPTABLE CONDITION AT TIME OF INSPECTION
--Other:	**OK**			